

PRIVATE HIRE INSPECTION ON TUK TUK REG M12 TUK 3.9.09

- 1 REAR SEAT HAS ONLY TWO 3POINT SEAT BELTS FITTED NO PROVISION FOR 3RD PASSENGER
REARWARD FACING SEAT IS FITTED WITH ONLY TWO LAP BELTS
 - 5 NO REAR VIEW MIRROR FITTED
 - 8 NO WINDOWS IN CAB OR PASSENGER COMPARTMENT
 - 9/34 WASHER JETS NOT OPERATING
 - 17 HANDBRAKE ON MAXIMUM TRAVEL
 - 39 INDICATOR FLASH RATE TOO FAST
 - 21 NO HEATER IN PASSENGER COMPARTMENT
 - 24 NO 'NO SMOKING' SIGNS FITTED
 - 26 FIRST AID KIT
 - 27 FIRE EXTINGUISHER READING EMPTY ON GAUGE
 - 30 NO DOORS IN DRIVERS COMPARTMENT OR PASSENGER COMPARTMENT
 - 53 EVIDENCE OF FUEL LEAK FROM TANK ON N/S +O/S REAR CORNERS
 - 54 EXHAUST CENTER BOX CRACKED AND BLOWING - REAR EXHAUST MOUNTING RUBBER MISSING (REPLACED WITH CABLE TIE)
 - 55 N/S REAR TOP SHACKLE BUSH COLLAPSED = REAR SHAKLE BUSHES EXCESIVE WEAR
 - 56 FRONT FORK SEAL LEAKING
 - 57 REAR SPRING LEAFS OUT OF ALLIGNMENT
 - 66 GREASE ON FRONT BRAKE DISC
 - 64 NO GROMMET PROTECTION ON FRONT BRAKE PIPE THROUGH BODY
- VEHICLE INCORRECT COLOUR
NO SIDE WEATHER PROTECTION FOR PASSENGERS



RE-TEST FOR PRIVATE HIRE INSPECTION ON TUK-TUK Agenda Item No. 7
REG M12 TUK 14.9.09

- 1 CENTER EXHAUST BOX BLOWING ON TOP OF EXIT PIPE
Repaired during test
- 2 RIGHT HAND SIDE REAR LEAF SPRING, HAS A LONGITUDINALY
DISPLACED LEAF
- 3 BATTERY INSECURE (Unable to inspect in original test as it was located
under passenger seat)
- 4 NO DOORS IN PASSENGER OR DRIVER AREA
- 5 NO WEATHER PROTECTION FOR PASSENGER OR DRIVERS AREA
BAR ROOF / FRONT WINDSCREEN
- 6 INCORRECT COLOUR